

From arc5 at ix.netcom.com Sat Mar 6 21:44:45 2021
From: arc5 at ix.netcom.com (David Stinson)
Date: Sat, 6 Mar 2021 15:44:45 -0600
Subject: [BoatAnchors] Very OT: IT Pros- need new laptop recommendation.
Message-ID: <a45dcef1-269f-28b6-8123-de1c2f4f6218@ix.netcom.com>

Very OT, but I ask here because I know many
of you are smart IT professionals.
Please reply only to me.
mailto: arc5 at ix.netcom.com

A dear friend is trying to replace an old laptop
that takes forever to boot and do anything.
She would like to buy a new with:

Windows.
Docking station available.
HD Video.
Able to connect to a large external monitor.
Fast.? SSD drive and large memory capacity.
RS-232 not needed.
Upgradeable, especially the battery.

Please recommend- I don't want to pretend
I know things I don't and hurt my friend.

Thank you kindly for your help,
Dave S.

--

This email has been checked for viruses by Avast antivirus software.
<https://www.avast.com/antivirus>

From anchor at ec.rr.com Tue Mar 9 15:52:53 2021
From: anchor at ec.rr.com (Al Parker)
Date: Tue, 9 Mar 2021 10:52:53 -0500
Subject: [BoatAnchors] DX-20 xfmr wanted
Message-ID: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>

hi folks,

A local friend said, "the stinky goo came out". He'd like a direct
repl., but anything that'll fit would get him going agn.

Orig. was:

Chicago Standard 5A-54 ser# 138044
Primary 117v. ac
Center tap 600v @ .120amps

6.3v @ 2amps and 5V @ 3amps

If you can help, pse let me know \$ & shipping to 28560.
tnx, 73,

Al, W8UT

www.boatanchors.org

www.hammarlund.info

"There is nothing -- absolutely nothing -- half so much
worth doing as simply messing about in boats"
Ratty, to Mole

From ajamas.rn at gmail.com Tue Mar 9 16:36:31 2021

From: ajamas.rn at gmail.com (Bob D.)

Date: Tue, 9 Mar 2021 11:36:31 -0500

Subject: [BoatAnchors] DX-20 xfmr wanted

In-Reply-To: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>

References: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>

Message-ID: <CA+kZa5phccjKJ=FMbr4kjSbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>

Al,

I used an Antec Toroidal for my Heathkit Williamson amp.

He'll need a dropping resistor or rectifier and 5V regulator.

I just said goodbye to the rectifier tube and went with a slightly lower
voltage transformer for my amp.

Here is a link to the 100 VA. It has 2 x 300 V windings @ 170 mA each and 2
x 6.3 V @ 3 A each windings

73, -Bob ah7i

On Tue, Mar 9, 2021 at 10:53 AM Al Parker <anchor at ec.rr.com> wrote:

> hi folks,

> A local friend said, "the stinky goo came out". He'd like a

> direct

> repl., but anything that'll fit would get him going agn.

> Orig. was:

> Chicago Standard 5A-54 ser# 138044

> Primary 117v. ac

> Center tap 600v @ .120amps

> 6.3v @ 2amps and 5V @ 3amps

> If you can help, pse let me know \$ & shipping to 28560.

> tnx, 73,

>

> Al, W8UT

> www.boatanchors.org

> www.hammarlund.info

>
> "There is nothing -- absolutely nothing -- half so much
> worth doing as simply messing about in boats"
> Ratty, to Mole
> -----
> BoatAnchors mailing list
> BoatAnchors at lists.theporch.com
> <https://lists.theporch.com/mailman/listinfo/boatanchors>
>

--

-do not look into LASER with remaining eye!

From ajamas.rn at gmail.com Tue Mar 9 16:40:06 2021
From: ajamas.rn at gmail.com (Bob D.)
Date: Tue, 9 Mar 2021 11:40:06 -0500
Subject: [BoatAnchors] DX-20 xfmr wanted
In-Reply-To: <CA+kZa5phccjKJ=FMbr4kjSbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>
References: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>
<CA+kZa5phccjKJ=FMbr4kjSbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>
Message-ID: <CA+kZa5pF04xtCbZ6YKTd4c3=KNZoEwYGLCumhtvr5tojU-pf5w@mail.gmail.com>

Al,

Sorry. Here is a link.

<https://www.antekinc.com/as-1t300-100va-300v-transformer/>
73, -bob ah7i

On Tue, Mar 9, 2021 at 11:36 AM Bob D. <ajamas.rn at gmail.com> wrote:

> Al,
>
> I used an Antec Toroidal for my Heathkit Williamson amp.
> He'll need a dropping resistor or rectifier and 5V regulator.
> I just said goodbye to the rectifier tube and went with a slightly lower
> voltage transformer for my amp.
> Here is a link to the 100 VA. It has 2 x 300 V windings @ 170 mA each and
> 2 x 6.3 V @ 3 A each windings
>
> 73, -Bob ah7i
>
> On Tue, Mar 9, 2021 at 10:53 AM Al Parker <anchor at ec.rr.com> wrote:
>
>> hi folks,
>> A local friend said, "the stinky goo came out". He'd like a
>> direct
>> repl., but anything that'll fit would get him going agn.

>> Orig. was:
>> Chicago Standard 5A-54 ser# 138044
>> Primary 117v. ac
>> Center tap 600v @ .120amps
>> 6.3v @ 2amps and 5V @ 3amps
>> If you can help, pse let me know \$ & shipping to 28560.
>> tn timer, 73,
>>
>> Al, W8UT
>> www.boatanchors.org
>> www.hammarlund.info
>>
>> "There is nothing -- absolutely nothing -- half so much
>> worth doing as simply messing about in boats"
>> Ratty, to Mole
>> -----
>> BoatAnchors mailing list
>> BoatAnchors at lists.theporch.com
>> https://lists.theporch.com/mailman/listinfo/boatanchors
>>
>
>
> --
> -do not look into LASER with remaining eye!
>

--

-do not look into LASER with remaining eye!

From john.shriver at gmail.com Tue Mar 9 18:27:08 2021
From: john.shriver at gmail.com (John Shriver)
Date: Tue, 9 Mar 2021 13:27:08 -0500
Subject: [BoatAnchors] DX-20 xfmr wanted
In-Reply-To: <CA+kZa5phccjKJ=FMbr4kjSbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>
References: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>
<CA+kZa5phccjKJ=FMbr4kjSbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>
Message-ID: <CAEv8c7H4sSh2bqeoF2LiwjB81qV7S4n0LR9vMjL5bD4VKMftQg@mail.gmail.com>

>From this document:
<http://akdatabase.com/AKview/albums/userpics/10007/Heathkit%20Power%20Transformers.pdf>,
the DX-20 uses a 600-0-600 secondary. Would be necessary to stack a pair of
the toroids. Which might not be a bad thing.

On Tue, Mar 9, 2021 at 11:37 AM Bob D. via BoatAnchors <
boatanchors at lists.theporch.com> wrote:

> Al,
>
> I used an Antec Toroidal for my Heathkit Williamson amp.
> He'll need a dropping resistor or rectifier and 5V regulator.
> I just said goodbye to the rectifier tube and went with a slightly lower
> voltage transformer for my amp.
> Here is a link to the 100 VA. It has 2 x 300 V windings @ 170 mA each and 2
> x 6.3 V @ 3 A each windings
>
> 73, -Bob ah7i
>
> On Tue, Mar 9, 2021 at 10:53 AM Al Parker <anchor at ec.rr.com> wrote:
>
> > hi folks,
> > A local friend said, "the stinky goo came out". He'd like a
> > direct
> > repl., but anything that'll fit would get him going agn.
> > Orig. was:
> > Chicago Standard 5A-54 ser# 138044
> > Primary 117v. ac
> > Center tap 600v @ .120amps
> > 6.3v @ 2amps and 5V @ 3amps
> > If you can help, pse let me know \$ & shipping to 28560.
> > tn timer, 73,
> >
> > Al, W8UT
> > www.boatanchors.org
> > www.hammarlund.info
> >
> > "There is nothing -- absolutely nothing -- half so much
> > worth doing as simply messing about in boats"
> > Ratty, to Mole
> > -----
> > BoatAnchors mailing list
> > BoatAnchors at lists.theporch.com
> > https://lists.theporch.com/mailman/listinfo/boatanchors
> >
>
>
> --
> -do not look into LASER with remaining eye!
> -----
> BoatAnchors mailing list
> BoatAnchors at lists.theporch.com
> https://lists.theporch.com/mailman/listinfo/boatanchors
>

From spr at earthlink.net Tue Mar 9 18:55:32 2021

From: spr at earthlink.net (Scott Robinson)
Date: Tue, 9 Mar 2021 10:55:32 -0800
Subject: [BoatAnchors] DX-20 xfmr wanted
In-Reply-To: <CAEv8c7H4sSh2bqeoF2LiwjB81qV7S4n0LR9vMjL5bD4VKMftQg@mail.gmail.com>
References: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>
<CA+kZa5phccjKJ=FMbr4kjSbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>
<CAEv8c7H4sSh2bqeoF2LiwjB81qV7S4n0LR9vMjL5bD4VKMftQg@mail.gmail.com>
Message-ID: <433843da-9fc6-dc06-b00c-3300dc20f9c8@earthlink.net>

Or put the two 300V windings on one transformer in series and use a silicon diode bridge of adequate voltage rating.

/scott

On 3/9/21 10:27 AM, John Shriver via BoatAnchors wrote:

>>From this document:

> [http://akdatabase.com/AKview/albums/userpics/10007/](http://akdatabase.com/AKview/albums/userpics/10007/Heathkit%20Power%20Transformers.pdf)

Heathkit%20Power%20Transformers.pdf,

> the DX-20 uses a 600-0-600 secondary. Would be necessary to stack a pair of
> the toroids. Which might not be a bad thing.

>

> On Tue, Mar 9, 2021 at 11:37 AM Bob D. via BoatAnchors <

> boatanchors at lists.theporch.com> wrote:

>

>> Al,

>>

>> I used an Antec Toroidal for my Heathkit Williamson amp.

>> He'll need a dropping resistor or rectifier and 5V regulator.

>> I just said goodbye to the rectifier tube and went with a slightly lower
>> voltage transformer for my amp.

>> Here is a link to the 100 VA. It has 2 x 300 V windings @ 170 mA each and 2
>> x 6.3 V @ 3 A each windings

>>

>> 73, -Bob ah7i

>>

>> On Tue, Mar 9, 2021 at 10:53 AM Al Parker <anchor at ec.rr.com> wrote:

>>

>>> hi folks,

>>> A local friend said, "the stinky goo came out". He'd like a

>>> direct

>>> repl., but anything that'll fit would get him going agn.

>>> Orig. was:

>>> Chicago Standard 5A-54 ser# 138044

>>> Primary 117v. ac

>>> Center tap 600v @ .120amps

>>> 6.3v @ 2amps and 5V @ 3amps

>>> If you can help, pse let me know \$ & shipping to 28560.

>>> tnx, 73,

```

>>>
>>> A1, W8UT
>>> www.boatanchors.org
>>> www.hammarlund.info
>>>
>>> "There is nothing -- absolutely nothing -- half so much
>>> worth doing as simply messing about in boats"
>>> Ratty, to Mole
>>> -----
>>> BoatAnchors mailing list
>>> BoatAnchors at lists.theporch.com
>>> https://lists.theporch.com/mailman/listinfo/boatanchors
>>>
>>
>>
>> --
>> -do not look into LASER with remaining eye!
>> -----
>> BoatAnchors mailing list
>> BoatAnchors at lists.theporch.com
>> https://lists.theporch.com/mailman/listinfo/boatanchors
>>
> -----
> BoatAnchors mailing list
> BoatAnchors at lists.theporch.com
> https://lists.theporch.com/mailman/listinfo/boatanchors
>

```

```

From ajamas.rn at gmail.com Tue Mar 9 19:28:56 2021
From: ajamas.rn at gmail.com (Bob D.)
Date: Tue, 9 Mar 2021 14:28:56 -0500
Subject: [BoatAnchors] DX-20 xfmr wanted
In-Reply-To: <CAEv8c7H4sSh2bqeoF2LiwjB81qV7S4n0LR9vMjL5bD4VKMftQg@mail.gmail.com>
References: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>
<CA+kZa5phccjKJ=FMbr4kjSbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>
<CAEv8c7H4sSh2bqeoF2LiwjB81qV7S4n0LR9vMjL5bD4VKMftQg@mail.gmail.com>
Message-ID: <CA+kZa5q3_oF=wb4kSWsC31=-f2YpwXP5PH6MC1vQLvCpvA1qw@mail.gmail.com>

```

I was thinking that it might. I get the old stuff mixed up.
 If he does away with the tube rectifier it's pretty easy to come up with
 the HV and no 5V worries.
 Antek has a 50VA transformer with 2 x 300 V windings. But, a pair will cost
 \$25 more than the single 100 VA.
 Here's an easy way to see what they offer.
<https://www.antekinc.com/grids/>

73, -bob ah7i

On Tue, Mar 9, 2021 at 1:27 PM John Shriver via BoatAnchors <boatanchors at lists.theporch.com> wrote:

> From this document:

>

> <http://akdatabase.com/AKview/albums/userpics/10007/Heathkit%20Power%20Transformers.pdf>

> ,

> the DX-20 uses a 600-0-600 secondary. Would be necessary to stack a pair of
> the toroids. Which might not be a bad thing.

>

> On Tue, Mar 9, 2021 at 11:37 AM Bob D. via BoatAnchors <boatanchors at lists.theporch.com> wrote:

>

> > Al,

> >

> > I used an Antec Toroidal for my Heathkit Williamson amp.

> > He'll need a dropping resistor or rectifier and 5V regulator.

> > I just said goodbye to the rectifier tube and went with a slightly lower
> > voltage transformer for my amp.

> > Here is a link to the 100 VA. It has 2 x 300 V windings @ 170 mA each
> > and 2

> > x 6.3 V @ 3 A each windings

> >

> > 73, -Bob ah7i

> >

> > On Tue, Mar 9, 2021 at 10:53 AM Al Parker <anchor at ec.rr.com> wrote:

> >

> > > hi folks,

> > > A local friend said, "the stinky goo came out". He'd like a

> > > direct

> > > repl., but anything that'll fit would get him going agn.

> > > Orig. was:

> > > Chicago Standard 5A-54 ser# 138044

> > > Primary 117v. ac

> > > Center tap 600v @ .120amps

> > > 6.3v @ 2amps and 5V @ 3amps

> > > If you can help, pse let me know \$ & shipping to 28560.

> > > tn timer, 73,

> > >

> > > Al, W8UT

> > > www.boatanchors.org

> > > www.hammarlund.info

> > >

> > > "There is nothing -- absolutely nothing -- half so much

> > > worth doing as simply messing about in boats"

> > > Ratty, to Mole


```
> > > -----
> > > BoatAnchors mailing list
> > > BoatAnchors at lists.theporch.com
> > > https://lists.theporch.com/mailman/listinfo/boatanchors
> > >
> >
> >
> > --
> > -do not look into LASER with remaining eye!
> > -----
> > BoatAnchors mailing list
> > BoatAnchors at lists.theporch.com
> > https://lists.theporch.com/mailman/listinfo/boatanchors
> >
> -----
> BoatAnchors mailing list
> BoatAnchors at lists.theporch.com
> https://lists.theporch.com/mailman/listinfo/boatanchors
>
```

--

-do not look into LASER with remaining eye!

From anchor at ec.rr.com Tue Mar 9 19:45:46 2021
From: anchor at ec.rr.com (Al Parker)
Date: Tue, 9 Mar 2021 14:45:46 -0500
Subject: [BoatAnchors] DX-20 xfmr wanted
In-Reply-To: <CA+kZa5q3_oF=wb4kSWsC31=-f2YpwXP5PH6MC1vQLvCpvA1qw@mail.gmail.com>
References: <21d0a7c7-f8cd-c04b-da6f-e8e7f9e247f5@ec.rr.com>
<CA+kZa5phccjKJ=FMbr4kjsbPZjz3e36ewdZAADtppfn_d+-=8Q@mail.gmail.com>
<CAEv8c7H4sSh2bqeoF2LiwjB81qV7S4n0LR9vMjL5bD4VKMftQg@mail.gmail.com>
<CA+kZa5q3_oF=wb4kSWsC31=-f2YpwXP5PH6MC1vQLvCpvA1qw@mail.gmail.com>
Message-ID: <c77fe9b9-909b-7437-8bd1-7b4fd137c8fe@ec.rr.com>

Hi Bob, et all,

Nice to hear from you, Bob, it's been a long time.

I agree with Scott & you, put the toroids sec.s in series and use a bridge rectifier. I think that'll probably be the cheapest way out, and will do everything exc. maintain originality.

orig. link:

<<https://www.antekinc.com/as-1t300-100va-300v-transformer/>>

73,

Al, W8UT

On 3/9/2021 2:28 PM, Bob D. via BoatAnchors wrote:

> I was thinking that it might. I get the old stuff mixed up.

> If he does away with the tube rectifier it's pretty easy to come up with
> the HV and no 5V worries.
> Antek has a 50VA transformer with 2 x 300 V windings. But, a pair will cost
> \$25 more than the single 100 VA.
> Here's an easy way to see what they offer.
> <https://www.antekinc.com/grids/>
>
> 73, -bob ah7i
>
>
> On Tue, Mar 9, 2021 at 1:27 PM John Shriver via BoatAnchors <
> boatanchors at lists.theporch.com> wrote:
>
>> From this document:
>>
>> [http://akdatabase.com/AKview/albums/userpics/10007/](http://akdatabase.com/AKview/albums/userpics/10007/Heathkit%20Power%20Transformers.pdf)
>> [Heathkit%20Power%20Transformers.pdf](http://akdatabase.com/AKview/albums/userpics/10007/Heathkit%20Power%20Transformers.pdf)
>> ,
>> the DX-20 uses a 600-0-600 secondary. Would be necessary to stack a pair of
>> the toroids. Which might not be a bad thing.
>>
>> On Tue, Mar 9, 2021 at 11:37 AM Bob D. via BoatAnchors <
>> boatanchors at lists.theporch.com> wrote:
>>
>>> Al,
>>>
>>> I used an Antec Toroidal for my Heathkit Williamson amp.
>>> He'll need a dropping resistor or rectifier and 5V regulator.
>>> I just said goodbye to the rectifier tube and went with a slightly lower
>>> voltage transformer for my amp.
>>> Here is a link to the 100 VA. It has 2 x 300 V windings @ 170 mA each
>> and 2
>>> x 6.3 V @ 3 A each windings
>>>
>>> 73, -Bob ah7i
>>>
>>> On Tue, Mar 9, 2021 at 10:53 AM Al Parker <anchor at ec.rr.com> wrote:
>>>
>>>> hi folks,
>>>> A local friend said, "the stinky goo came out". He'd like a
>>>> direct
>>>> repl., but anything that'll fit would get him going agn.
>>>> Orig. was:
>>>> Chicago Standard 54-54 ser# 138044
>>>> Primary 117v. ac
>>>> Center tap 600v @ .120amps
>>>> 6.3v @ 2amps and 5V @ 3amps
>>>> If you can help, pse let me know \$ & shipping to 28560.

>>>> tnx, 73,
>>>>
>>>> A1, W8UT

From arc5 at ix.netcom.com Wed Mar 10 00:44:46 2021
From: arc5 at ix.netcom.com (David Stinson)
Date: Tue, 9 Mar 2021 18:44:46 -0600
Subject: [BoatAnchors] Drake Fans in North Houston
Message-ID: <78caaa4e-f17a-83e4-4d01-169abe9c0240@ix.netcom.com>

If you're in North Houston and you're a Drake fan,
you might want to check this out:
<https://www.facebook.com/marketplace/item/2861515214169261/>

--

This email has been checked for viruses by Avast antivirus software.
<https://www.avast.com/antivirus>

From arc5 at ix.netcom.com Wed Mar 10 22:10:43 2021
From: arc5 at ix.netcom.com (David Stinson)
Date: Wed, 10 Mar 2021 16:10:43 -0600
Subject: [BoatAnchors] More Radios
Message-ID: <36e568fe-1a50-6a84-0d98-d18506efe6dc@ix.netcom.com>

--

This email has been checked for viruses by Avast antivirus software.
<https://www.avast.com/antivirus>

From thompson at mindspring.com Fri Mar 26 14:55:01 2021
From: thompson at mindspring.com (Dave Thompson)
Date: Fri, 26 Mar 2021 10:55:01 -0400 (GMT-04:00)
Subject: [BoatAnchors] test message
Message-ID: <896668625.2240.1616770501394@wamui-dingo.atl.sa.earthlink.net>

This test message is being sent as I get messages but cannot send messages.

Dave K4JRB

-

From spr at earthlink.net Fri Mar 26 15:02:07 2021
From: spr at earthlink.net (Scott Robinson)
Date: Fri, 26 Mar 2021 08:02:07 -0700

Subject: [BoatAnchors] test message
In-Reply-To: <896668625.2240.1616770501394@wamui-dingo.atl.sa.earthlink.net>
References: <896668625.2240.1616770501394@wamui-dingo.atl.sa.earthlink.net>
Message-ID: <53dd6445-ecb3-0a99-d9b4-d33fb5a20b4b@earthlink.net>

Message received here via the list.

/scott

On 3/26/21 7:55 AM, Dave Thompson via BoatAnchors wrote:

>
>
> This test message is being sent as I get messages but cannot send messages.
>
> Dave K4JRB
> -
> -----
> BoatAnchors mailing list
> BoatAnchors at lists.theporch.com
> <https://lists.theporch.com/mailman/listinfo/boatanchors>
>

From thompson at mindspring.com Fri Mar 26 15:14:37 2021
From: thompson at mindspring.com (Dave Thompson)
Date: Fri, 26 Mar 2021 11:14:37 -0400 (GMT-04:00)
Subject: [BoatAnchors] test message
Message-ID: <558384799.2565.1616771677784@wamui-dingo.atl.sa.earthlink.net>

Looks like I am receiving messages again. Thanks. Is W4KH still the moderator of the list?

73 Dave K4JRB

From ppporch at theporch.com Fri Mar 26 15:58:26 2021
From: ppporch at theporch.com (Phillip Porch)
Date: Fri, 26 Mar 2021 10:58:26 -0500
Subject: [BoatAnchors] test message
In-Reply-To: <896668625.2240.1616770501394@wamui-dingo.atl.sa.earthlink.net>
References: <896668625.2240.1616770501394@wamui-dingo.atl.sa.earthlink.net>
Message-ID: <E327D5B5-6D11-4C25-9F46-32A5665C714B@theporch.com>

I got it.

Phillip Porch, MD

> On Mar 26, 2021, at 9:55 AM, Dave Thompson via BoatAnchors <boatanchors at lists.theporch.com> wrote:

>

> ?

>

> This test message is being sent as I get messages but cannot send messages.

>

> Dave K4JRB

> -

>

> -----
> BoatAnchors mailing list

> BoatAnchors at lists.theporch.com

> <https://lists.theporch.com/mailman/listinfo/boatanchors>

From k1lky68 at gmail.com Sat Mar 27 03:46:42 2021

From: k1lky68 at gmail.com (Roy Morgan)

Date: Fri, 26 Mar 2021 23:46:42 -0400

Subject: [BoatAnchors] Wilcox 602A Receivers

In-Reply-To: <36e568fe-1a50-6a84-0d98-d18506efe6dc@ix.netcom.com>

References: <36e568fe-1a50-6a84-0d98-d18506efe6dc@ix.netcom.com>

Message-ID: <42BB0141-56B3-4592-8133-CE9E33DFD0F3@gmail.com>

Boatanchor folks,

While rummaging in the barn among long-neglected Junque and Treasures, I found two Wilcox 602A Receivers.

These things are octal tubed (with one 7-pin miniature) rack mount VHF fixed frequency receivers used in airport towers and FAA flight control stations. Mine are marked 147.4 mc. One has the crystal installed and so I can figure out the IF frequency.

I have searched the internet and the Wayback Machine (<https://archive.org/>) and have not found any reference to these.

Does anyone have info on them?

Thanks,

Roy

Roy Morgan

K1LKY since 1958

k1lky68 at gmail.com

Western Mass